

CARR - 664

OLD WESTMINSTER ROAD HOUSE

mid 19th century

Westminster vicinity

private

Two-story, four-bay by two-bay house with an L-shaped plan. Contains two entrances in the central two bays in a manner found throughout German-settled regions of Pennsylvania, Maryland and Virginia. Exterior woodwork dates from the mid-to-late nineteenth century. The house is a representative farmhouse from the mid-to-late nineteenth century. It is currently uninhabited.



## DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street  
Westminster, Maryland 21157

## WESTMINSTER PLANNING DISTRICT

## FIELD SHEET--HISTORIC RESOURCES SURVEY

2/18

SURVEY NUMBER:

CARR-664

NEGATIVE FILE NUMBER:

UTM REFERENCES:

Zone/Easting/Northing

U.S.G.S. QUAD. MAP:

New Windsor

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE:

abandoned

ORIGINAL USE:

residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent ( )

Good ( )

Fair (X)

Poor ( )

THEME:

STYLE:

DATE BUILT:

mid. 19th century

COUNTY:

CARROLL

TOWN:

Westminster vicinity

LOCATION:

east side of Old Westminster Road  
1/2 mile north of Stone Chapel Road

COMMON NAME:

FUNCTIONAL TYPE:

residence

OWNER:

ADDRESS:

Clifford E. Still  
232 Church St.  
New Windsor MD 21776

ACCESSIBILITY TO PUBLIC:

Yes ( )

No (X)

Restricted ( )

LEVEL OF SIGNIFICANCE:

Local ( )

State ( )

National ( )

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )

2. Wall Structure

A. Wood: Log ( ) Post and Beam (X) Balloon ( )

B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )

C. Iron ( ) D. Steel ( ) E. Other

3. Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum (X) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other:

4. Roof Structure

A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )

B. Other:

5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle (X) Sheet Metal ( )  
Built Up ( ) Rolled ( ) Tile ( ) Other:

6. Engineering Structure:

7. Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells (X) Wings ( ) Other:Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories:

2

Number of Bays:

4x2

Approximate Dimensions:

Entrance Location:

double entrance - 2  
central bays

THREAT TO STRUCTURE:

No Threat ( ) Zoning ( ) Roads ( )

Development ( ) Deterioration (X)

Alteration ( ) Other:

LOCAL ATTITUDES:

Positive ( ) Negative ( )

Mixed ( ) Other:

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

German style two entrances in 2 central bays  
mid-19th century woodwork on exterior details

## RELATED STRUCTURES: (Describe)

none

## STATEMENT OF SIGNIFICANCE:

representative mid-19th c. farmhouse

## REFERENCES:

1862 Martenet's Map: 7

1877 LG & S Atlas:

map 51 p. 16

336/448

## SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up ( ) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:

## RECORDED BY:

Joe Getty

## ORGANIZATION:

## DATE RECORDED:



U.S.G.S. MAP  
NEW WINDSOR, MD.  
1:24000 SCALE



1. CARR-664 Old Westminster Road
2. Carroll County, Maryland
3. Joe Getty
4. August 1983
5. Md. Historical Trust, Annapolis, Md.
6. West elevation; camera facing east
7. 1/1